



General Usage

| | |
|-------------------------|----------|
| New File | Ctrl + N |
| Open File | Ctrl + O |
| Close File | Ctrl + W |
| Save File | Ctrl + S |
| Print File | Ctrl + P |
| Undo | Ctrl + Z |
| Redo | Ctrl + Y |
| Cut | Ctrl + X |
| Copy | Ctrl + C |
| Paste | Ctrl + V |
| Quick Rebuild | Ctrl + B |
| Forced (Total) Rebuild | Ctrl + Q |
| Delete | Delete |
| Repeat Last Command | Enter |
| Help Menu | H |
| Rename Selected Feature | F2 |
| Spell Checker | F7 |
| Search SOLIDWORKS Help | H |
| Search Knowledge Base | K |
| Search Community Forum | O |
| Search Commands | W |

Toolbars & Windows

| | |
|------------------------------------|--------------------|
| User-Defined Toolbar | S |
| User-Defined Mouse Gestures | Right Click + Drag |
| Hide/Show Display Pane | F8 |
| Hide/Show Feature Manager Tree | F9 |
| Hide/Show All Active Toolbars | F10 |
| Full Screen Mode On/Off | F11 |
| Hide/Show Task Pane | Ctrl + F1 |
| Collapse All Items in Feature Tree | Shift + C |
| Scroll to Top of Feature Tree | Home |
| Scroll to Bottom of Feature Tree | End |

Views

| | |
|------------------------------|------------------|
| Toolbar of View Orientations | Spacebar |
| View Selector Cube | Ctrl + Spacebar |
| Front View | Ctrl + 1 |
| Back View | Ctrl + 2 |
| Left View | Ctrl + 3 |
| Right View | Ctrl + 4 |
| Top View | Ctrl + 5 |
| Bottom View | Ctrl + 6 |
| Isometric View | Ctrl + 7 |
| Normal to View | Ctrl + 8 |
| Previous View | Ctrl + Shift + Z |
| Take Snapshot | Alt + Spacebar |

Zoom & Rotation

| | |
|----------------------------|----------------------|
| Zoom Out | Z |
| Zoom In | Shift + Z |
| Zoom to Fit | F |
| Magnifying Glass | G |
| Rotate View 15 Degrees | Arrow Keys |
| Rotate View 90 Degrees | Shift + Arrow Keys |
| Pan View | Ctrl + Arrow Keys |
| Roll View to Normal Screen | Alt + L/R Arrow Keys |

Interlink Recommends You Add:

| | |
|--------------------------|-----------|
| Open File Properties | Shift + P |
| View Planes | P |
| View Sketches | Ctrl + K |
| View Sketch Relations | R |
| Move Controls to Pointer | D |
| Measure Tool On/Off | M |
| Windows, Tile Vertically | T |
| Windows, Close All | Alt + W |